

Digital Hygrometer

Model: FPDH50



- ❖ Humidity / Barometer / Temperature Monitor
- ❖ Humidity: 10 to 90% RH
- ❖ Temperature: 0 to 50.0°C
- ❖ Barometer: 10 to 1100hPa, 7.5 to 825.0 mmHg in 0.29 to 32.48Hg
- ❖ Shows barometer, humidity and temperature values in the same LCD
- ❖ Low power consumption and long battery life when using battery power
- ❖ RS232 / USB computer interface
- ❖ Power Source: DC 1.5V battery × 6 PCs